## DUCHESNE COUNTY, UTAH - SURVEY MONUMENT RECORD

SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET. Also, indicate scale and basis of bearings.

Point ties from the East 1/4 Corner of Section 5 to neighboring Section

- 1. The West 1/4 Corner of Section 5, being an aluminum cap, bears S89°09'33"W 5246.34'.
- 2. The Closing Corner for the Northeast Corner of Section 5, being a set, marked stone, bears N00°04'05"E 2666.70' (Basis of Bearings).


Set 1/2" rebar with maroon plastic cap, stamped LS 10325987, RM.

Mound of Stones


S66°38'E 46.05' O Reference Point: Set 1/2" rebar with maroon plastic cap, stamped LS 10325987, RM.

East 1/4 Corner of Section 5, T4S, R4W, U.S.M.: Found 1/2" Rebar with a yellow plastic cap (unreadable) protruding 0.3' above ground, surrounded by a mound of stones, 1.5' base, 0.6' high.

Not to Scale Drawn By: SMR



Corner Monument Markings - Photo View or Stamping on Cap



COORDINATES DETERMINED FROM: UTAH REFERENCE NETWORK CONTROL SYSTEM NAD 83 2011 EPOCH 2010

GEOID 12A, NAVD 88 ELEVATION = 5711.9'

STATE PLANE COORDINATES

"UTAH COORDINATE SYSTEM 1983 CENTRAL ZONE"

NORTHING = 7,230,079.417'

EASTING = 1,961,380.139'

**GEOGRAPHIC COORDINATES - NAD 83** 

LATITUDE =  $40^{\circ}09'46.01968"N$ 

 $LONGITUDE = 110^{\circ}21'05.42995"W$ 

ELLIPSOID HEIGHT = 5655.199'



PHOTO OF CORNER

## CERTIFICATION

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Surveyor's Name (Please Print):


Timberline Engineering and Land Surveying, Inc. Firm Name: \_\_\_

209 North 300 West Vernal, Utah 84078 Firm Address:\_\_\_

10325987 Survey Date: 12-21-18 Utah License Number: \_\_

LOCATION DIAGRAM

1" = 1 Mile



= Location of Monument



Signature/Date through Seal

**4S**  $R_4W$ SEC <u>.. U.S.</u> м.